

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

got

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter

Division Director

 1594 West North Temple, Suite 1210
 Partial: XXX Complete: Exploration: Exploration: Date & Time: 9/23/97 / 12:30p.m.-4:30p.m.

 801) 538-5340 (801) 359-3940 (Fax)
 Date of Last Inspection: 8/5 & 12/97

Mine Name: Bear Canyon Mine County: Emery Permit Number: ACT/015/025						
Permittee and/or Operator's Name: Co-Op Mining Company						
Business Address: P. O. Box 1245, Huntington, Utah 84528						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Charles Reynolds						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Cool, Clear, 70's						
Existing Acreage: Permitted-1531 Disturbed-24 Regraded-0 Seeded-0 Bonded-24						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<u>EVALUATED</u>	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		\Box		П
2.	SIGNS AND MARKERS	[XX]	Ц	\Box	\Box
3.	TOPSOIL	[XX]	Ц	\Box	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX] []	Ш	[XX]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	П	Ц	\Box	
c.	OTHER SEDIMENT CONTROL MEASURES	\Box	Ш	ĹĬ	ĹÌ
d.	WATER MONITORING	ĹĬ	ĹÌ	\Box	\Box
e.	EFFLUENT LIMITATIONS	\Box	ĹĬ	ĹĬ	ĹÌ
5.	EXPLOSIVES	ĹĬ	Ĺ	П	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	Ĺ	Ĺ	ĹÌ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	Ĺ	ĹÌ	Ц	ĹÌ
8.	NONCOAL WASTE	[XX]	П	ĹĬ	ĹÌ
9.	PROTECTION OF FISH, WILDLIFE AND	-			
	RELATED ENVIRONMENTAL VALUES	\Box	Ц	Ш	\Box
10.	SLIDES AND OTHER DAMAGE	ĹĬ	ĹÌ	Ш	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	Ц	Ĺĺ	Ĺĺ
12.	BACKFILLING AND GRADING	Ĺĺ	\Box	\Box	\Box
13.	REVEGETATION	Ĺĺ	\Box	\Box	\Box
14.	SUBSIDENCE CONTROL	\Box	ĹĬ	ĹÌ	\Box
15.	CESSATION OF OPERATIONS	\Box	Ш	\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX] [XX] [_]	\Box	[XX]	\Box
b.	DRAINAGE CONTROLS	[XX]	Ĺĺ	Ц	\Box
17.	OTHER TRANSPORTATION FACILITIES	Ц	Ш	\Box	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	\Box	\Box	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date)			Ĺ	
20.	AIR QUALITY PERMIT		ĹĬ	LÌ	\Box
21.	BONDING & INSURANCE		ĹÌ	ĹĴ	LĪ



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 9/23/97

(Comments are Numbered to Correspond with Topics Listed Above)

4a. HYDROLOGIC BALANCE: DIVERSIONS

Ditch D-7D which lies on the SW corner of the clean coal storage pad is in dire need of work. The ditch, as observed this day, is undercutting the water tank and is heavily eroded in other locations. Page 7-87, Table 7.2-10 shows top and bottom width dimensions of 2 feet and 3.5 feet respectively. Although the ditch generally meets the specification requirements, erosion of the banks caused by meandering water has caused the problem. Mr. Reynolds is aware that the repair of this ditch is a high priority. It may be necessary to consider either grouting of this ditch in areas where high velocity water is cutting the banks or placing riprap where the flows must make turns. The section of D-7D that makes the drop in elevation from the stockpile pad to the new bath house should be re-evaluated for adequate erosion protection.

16a. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Permit amendment ACT/015/025-97B, which relates to the blacktop surfacing of the roadway in the area of the scale house has been re-activated and is under review in the PFO. The permittee is trying to determine the type of mix to be used in this area at the request of this inspector. Bond calculations have been adjusted for the removal and disposal of the 260 yards of material in a State certified landfill.

This inspector is concerned that if a standard mix is used in the scalehouse area, hot summer temperatures and the heavy coal trucks may cause rutting of the new surface. Additional material may need to be placed in these ruts, creating additional costs by having a higher volume of material which must be disposed of. The permittee may be able to show that the current bond has enough extra dollars already in place to handle the extra material. A response from the permittee is pending.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Charles Reynolds (Co-Op) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office

Date: October 2, 1997

Inspector's Signature: #46

Peter Hess